These instructions do not claim to cover all details or variations in equipment, nor to provide for all possible conditions to be met concerning installation, operation, or maintenance of this equipment. The presence of energized overhead lines in particular may necessitate alternate methods to prevent accidental contact with the lines. If further information is desired or if particular problems are encountered which are not sufficiently covered in this guide, contact A. B. Chance Company.

NOTE: Because Hubbell has a policy of continuous product improvement, were serve the right to change design and specifications without notice.

©1998 Hubbell/Chance

Printed in USA



# Chance LoadLooker Ammeter Catalog No. MEAMP11RW & MEAMP12RW

## **Operator's Manual**

#### **Safety Information**

The LoadLooker is designed for both hand-held use and for use when attached to a suitable universal hot stick. All precautions appropriate for the line voltage should be taken. The hot stick should be considered the sole voltage isolation device.

#### **Specifications**

The LoadLooker has been developed specifically for measurement of AC current in the electrical utility industry. This instrument can be used remotely with any hotstick and universal adapter or can be hand held for use on voltages less than 600V. It will measure current up to 2,000 amperes, on two auto-ranging scales. The instrument has no moving parts and does not require clamping onto the wire. The instrument case is water resistant and high-impact resistant.

The True RMS feature allows accurate measurement of current even when the nominal waveform is distorted or when harmonics are present. This may be the case with Y connected transformer neutral leads and distribution to many industrial customers using SCR controllers and other switching devices.

The following specifications apply:

**Operating voltage:** 1 to 69kV phase-to-phase when mounted any appropriate length hot stick **with universal adapter** 

Jaw capacity: 3.86" (9.8 cm) LCD display:  $3\frac{1}{2}$ -digit True RMS

**0 - 2,000 amperes** with ±1% accuracy — Cat. No. MEAMP11RW **0 - 5,000 amperes** with ±1% accuracy — Cat. No. MEAMP12RW

**Auto-ranging:** Cat. No. MEAMP11RW: 0 to 200 amp (0.1 amp resolution) 200 to 2,000 amp (1 amp resolution)

Cat. No. MEAMP12RW: 0 to 200 amp (0.1 amp resolution)
200 to 2,000 amp (1 amp resolution)
2,000 to 5,000 amp (0.01 kamp resolution)

**No moving parts** — Just slide wire between jaws.

**Peak current hold** — Position instrument in hard-to-see location with hotstick, then pull back to read current close up.

**Temperature range:** -30° to 60° C (-22° to 140° F)

9 volt battery power, long battery life, low battery indicator on display

One button operation with automatic power-off timer

Automatic power-off after several minutes of no activity

# Chance LoadLooker Ammeter Catalog No. MEAMP11RW & MEAMP12RW

#### **Operating Instructions**

The LoadLooker is controlled by the single push button switch located on the front panel, and is operated as follows:

#### Press the control switch momentarily to turn on the LoadLooker.

The LoadLooker is now in the normal measurement mode and the reading will continuously change as the current changes. To use the LoadLooker in this mode, place the current carrying wire between the two legs and observe the display. To ensure maximum accuracy, be sure the wire is below the notches on the legs. If the wire cannot be placed below the notches, readings can be taken but accuracy will be somewhat reduced.

#### **△WARNING**

Do not force or stress arms of the LoadLooker.

The True RMS LoadLooker will display the following as it conducts a start-up calibration process:

1.8.8.8 CAL 0.0

### 2. Press the control switch a second time to go to the sample and hold mode.

The LoadLooker is now in the sample and hold mode and this is indicated by the word "HOLD" appearing in the display. It will retain the highest reading reached before being reset. This allows it to be placed around the current carrying wire, and then returned to eye level where it may be easily read.

### 3. Press the control switch a third time to clear the sample and hold reading.

The LoadLooker is now returned to the normal mode. Alternate switch actuations change the LoadLooker between the normal mode and the sample and hold mode. Observe the word "HOLD" in the display to determine which mode the unit is in.

## 4. The LoadLooker will turn itself off automatically after several minutes of inactivity.

If it is desired to turn the unit off manually, press and hold the button down for 4 to 5 seconds.

#### **High-Voltage Operation**

This instrument is designed to operate in high voltage fields. However, difficulty may be experienced when excessive corona to the instrument occurs. The unit may experience over range and require power to be cycled or may lose a reading when in the sample and hold mode. This may occur when the operating voltage load is exceeded.

#### **Battery Replacement**

When the "LO BAT" indication shows on the display, the battery should be replaced. The unit will continue to operate for a few hours. The LoadLooker is powered by a single 9V battery. To replace the battery, remove the four screws on the battery cover at the rear of the unit. Carefully insert a screwdriver blade in the notch and pry the cover out, being careful not to damage the cover seal. Pull the battery out of the compartment and separate the battery from the battery connector. To avoid breaking the battery leads do not pull on the battery only. Install a fresh battery and reinsert the battery in its compartment. Reinstall the cover by gently pressing it into place while pulling out on the edges of the compartment, and reinstall the four cover screws. Take care to avoid overtightening the screws. Always reuse the screws provided and do not damage or lose the o-ring seal on each screw.

#### Cleaning

The LoadLooker can be cleaned by wiping with a small amount of alcohol on a rag. Do not use too much alcohol and use it only on the urethane case. Do not get the alcohol on the front or rear panels. The paint and lettering will be damaged by alcohol.