# ACCESSORY:
# SIGNAL CABLE SELECTION GUIDE

Select from the catalog breakdown table options below. Enter the desired selection in the corresponding position.

**PSC820**   **2**   **X**   **1**   **X X**

| | | | |
|:---:|:---:|:---:|:---:|
| 1 | 2 | 3 | 4 |

| Position No. | Description | Options |
|:---:|:---:|:---:|
| 1 | Product Type | 2 = Cables and Accessories |
| 2 | Connector on the Sensor Side | 1 = CVMI CONNECTOR 4-PIN<br>2 = CMI CONNECTOR 2-PIN |
| 3 | Connector on the Instrument Side | 1 = No terminal (Lead Wires)* |
| 4 | Length of the Cable | XX - Length of Signal Cable (in FT)** |

\* No terminal (pigtail) is the standard offering.  Please contact your local Hubbell Representative for other options on cables.

\** Length options are between 0 to 50 ft. (ex. PSC8202XX05; PSC8202XX25; PSC8202XX50).  Standard lengths are 20', 30', 40' and 50'.