



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.:	GB/BAS/QAR06.0061/10	Page 1 of 5
QAR Free Ref. No.:	0500	Status: Issued
Details of change:	Re-assessment audit completed	Date of issue: 2022-11-28
Site(s) audited:	Hawke International A Division of Hubbell Limited A Member of the Hubbell Group of Companies Oxford Street West Ashton-under-Lyne Lancashire OL7 0NA United Kingdom	Valid until: 2025-11-03 Audit date: 2022-11-03
Issuing ExCB:	BAS - SGS Baseefa Limited	
Manufacturer:	Hawke International A Division of Hubbell Limited A Member of the Hubbell Group of Companies Oxford Street West Ashton-under-Lyne Lancashire OL7 0NA	
Location of Manufacturer:	United Kingdom	
Product information:	Cable Glands, connectors and associated accessories	
Protection concept:	Ex "d", "e", "i", "t", "n", "op is", "op pr"	
Related QARs:		
GB/BAS/QAR06.0061/00	GB/BAS/QAR06.0061/01	GB/BAS/QAR06.0061/02
GB/BAS/QAR06.0061/03	GB/BAS/QAR06.0061/04	GB/BAS/QAR06.0061/05
GB/BAS/QAR06.0061/06	GB/BAS/QAR06.0061/07	GB/BAS/QAR06.0061/08
GB/BAS/QAR06.0061/09		
Related Certificates (manual insertion)::		
Related Certificates (automatic linking)::		
Related Certificates for previous versions:		
IECEX BAS 06.0013X issue: 2	IECEX BAS 06.0013X issue: 3	IECEX BAS 06.0013X issue: 4
IECEX BAS 06.0013X issue: 5	IECEX BAS 06.0013X issue: 6	IECEX BAS 06.0013X issue: 7
IECEX BAS 06.0013X issue: 8	IECEX BAS 06.0013X issue: 9	IECEX BAS 06.0013X issue: 10
IECEX BAS 06.0013X issue: 11	IECEX BAS 06.0013X issue: 12	IECEX BAS 06.0013X issue: 0
IECEX BAS 06.0014X issue: 1	IECEX BAS 06.0014X issue: 2	IECEX BAS 06.0014X issue: 3
IECEX BAS 06.0014X issue: 4	IECEX BAS 06.0014X issue: 5	IECEX BAS 06.0014X issue: 6
IECEX BAS 06.0014X issue: 7	IECEX BAS 06.0014X issue: 8	IECEX BAS 06.0014X issue: 9
IECEX BAS 06.0014X issue: 10	IECEX BAS 06.0014X issue: 11	IECEX BAS 06.0015X issue: 1
IECEX BAS 06.0015X issue: 2	IECEX BAS 06.0015X issue: 3	IECEX BAS 06.0015X issue: 4
IECEX BAS 06.0015X issue: 5	IECEX BAS 06.0015X issue: 6	IECEX BAS 06.0015X issue: 7
IECEX BAS 06.0015X issue: 8	IECEX BAS 06.0015X issue: 9	IECEX BAS 06.0015X issue: 10
IECEX BAS 06.0015X issue: 11	IECEX BAS 06.0015X issue: 12	IECEX BAS 06.0015X issue: 13
IECEX BAS 06.0015X issue: 14	IECEX BAS 06.0016X issue: 1	IECEX BAS 06.0016X issue: 2
IECEX BAS 06.0016X issue: 3	IECEX BAS 06.0016X issue: 4	IECEX BAS 06.0016X issue: 5
IECEX BAS 06.0016X issue: 6	IECEX BAS 06.0016X issue: 7	IECEX BAS 06.0016X issue: 8
IECEX BAS 06.0016X issue: 9	IECEX BAS 06.0016X issue: 10	IECEX BAS 06.0016X issue: 11
IECEX BAS 06.0016X issue: 12	IECEX BAS 06.0017X issue: 1	IECEX BAS 06.0017X issue: 2
IECEX BAS 06.0017X issue: 3	IECEX BAS 06.0017X issue: 4	IECEX BAS 06.0017X issue: 5
IECEX BAS 06.0017X issue: 6	IECEX BAS 06.0018X issue: 2	IECEX BAS 06.0018X issue: 3



IECEX Quality Assessment Report Summary

QAR Ref. No.: **GB/BAS/QAR06.0061/10**

Page 3 of 5

Related Certificates for
previous versions (continued):

IECEX BAS 11.0079X issue: 3	IECEX BAS 11.0079X issue: 4	IECEX BAS 11.0079X issue: 5
IECEX BAS 11.0079X issue: 6	IECEX BAS 12.0006X issue: 0	IECEX BAS 12.0006X issue: 1
IECEX BAS 12.0006X issue: 2	IECEX BAS 12.0006X issue: 3	IECEX BAS 12.0006X issue: 4
IECEX BAS 12.0006X issue: 5	IECEX BAS 12.0006X issue: 6	IECEX BAS 12.0006X issue: 7
IECEX BAS 12.0006X issue: 8	IECEX BAS 12.0006X issue: 9	IECEX BAS 12.0006X issue: 10
IECEX BAS 12.0006X issue: 11	IECEX BAS 12.0065X issue: 0	IECEX BAS 12.0065X issue: 1
IECEX BAS 12.0065X issue: 2	IECEX BAS 12.0065X issue: 3	IECEX BAS 12.0111X issue: 0
IECEX BAS 12.0111X issue: 1	IECEX BAS 12.0111X issue: 2	IECEX BAS 12.0111X issue: 3
IECEX BAS 14.0002U issue: 0	IECEX BAS 14.0002U issue: 1	IECEX BAS 14.0002U issue: 2
IECEX BAS 14.0002U issue: 3	IECEX BAS 14.0120U issue: 0	IECEX BAS 14.0120U issue: 0
IECEX BAS 14.0120U issue: 1	IECEX BAS 14.0120U issue: 2	IECEX BAS 14.0120U issue: 3
IECEX BAS 14.0120U issue: 4	IECEX BAS 14.0120U issue: 5	IECEX BAS 14.0120U issue: 6
IECEX BAS 14.0123X issue: 0	IECEX BAS 14.0123X issue: 1	IECEX BAS 14.0123X issue: 2
IECEX BAS 14.0123X issue: 3	IECEX BAS 14.0123X issue: 4	IECEX BAS 14.0123X issue: 5
IECEX BAS 14.0123X issue: 6	IECEX BAS 14.0144X issue: 0	IECEX BAS 14.0144X issue: 1
IECEX BAS 15.0106X issue: 0	IECEX BAS 16.0032X issue: 0	IECEX BAS 16.0032X issue: 1
IECEX BAS 16.0032X issue: 2	IECEX BAS 16.0032X issue: 3	IECEX BAS 16.0058X issue: 0
IECEX BAS 16.0090X issue: 0	IECEX BAS 17.0031U issue: 0	IECEX BAS 17.0031U issue: 1
IECEX BAS 18.0027X issue: 0	IECEX BAS 18.0030X issue: 0	IECEX CES 19.0013X issue: 0
IECEX CES 19.0013X issue: 1	IECEX CES 19.0014X issue: 0	IECEX CES 19.0014X issue: 1
IECEX CML 18.0131X issue: 0	IECEX CML 18.0131X issue: 1	IECEX CML 18.0131X issue: 2
IECEX CML 18.0131X issue: 3	IECEX CML 19.0042X issue: 0	IECEX CML 19.0042X issue: 1
IECEX CML 19.0043X issue: 0	IECEX CML 19.0043X issue: 1	IECEX CML 19.0044X issue: 0
IECEX CML 19.0044X issue: 1	IECEX CML 19.0045X issue: 0	IECEX CML 19.0045X issue: 1
IECEX CML 19.0045X issue: 2	IECEX CML 19.0047X issue: 0	IECEX CML 19.0047X issue: 1
IECEX CML 19.0048X issue: 0	IECEX CML 19.0048X issue: 1	IECEX CML 19.0145X issue: 0
IECEX CML 20.0137X issue: 0	IECEX CML 20.0137X issue: 1	IECEX CML 21.0012X issue: 0
IECEX CML 21.0012X issue: 1	IECEX SIR 06.0082X issue: 0	IECEX SIR 06.0082X issue: 1
IECEX SIR 06.0082X issue: 2	IECEX SIR 06.0082X issue: 3	IECEX SIR 06.0082X issue: 4
IECEX SIR 06.0082X issue: 5	IECEX SIR 06.0082X issue: 6	IECEX SIR 06.0082X issue: 7
IECEX SIR 06.0082X issue: 8	IECEX SIR 06.0082X issue: 9	IECEX SIR 11.0088X issue: 0
IECEX SIR 11.0094X issue: 0	IECEX SIR 11.0094X issue: 1	IECEX SIR 11.0152U issue: 0
IECEX SIR 11.0152U issue: 1	IECEX SIR 11.0152U issue: 2	IECEX SIR 11.0152U issue: 3
IECEX SIR 11.0152U issue: 4	IECEX SIR 12.0030X issue: 0	IECEX SIR 12.0030X issue: 1
IECEX SIR 12.0046X issue: 0	IECEX TSA 17.0012U issue: 0	IECEX UL 15.0054X issue: 1
IECEX UL 15.0054X issue: 2	IECEX UL 15.0054X issue: 3	IECEX UL 15.0054X issue: 4

Comments: The following assemblers are accepted in accordance with OD203.

Cable Systems Ltd
2-6 Gawsworth Court
Risley Road
Birchwood
Warrington, Cheshire
WA3 6NJ

Limitation of Scope - Assembly of Junction boxes
Protection Concepts - Ex 'e' 'tb'

Industrial Systems Group (ISG)
2nd Industrial Area, PO Box 4
31411 Dammam
Kingdom of Saudi Arabia
Limitation of Scope - Assembly of Junction boxes
Protection Concepts - Ex 'e' 'tb'

MacLean Electrical (Australia) Pty Ltd
93 Inspiration Drive,
Wangara,
Perth 6065,
Australia
Limitation of Scope - Assembly of Junction boxes
Protection Concepts - Ex 'e' 'tb'



IECEX Quality Assessment Report Summary

QAR Ref. No.:

GB/BAS/QAR06.0061/10

Page 4 of 5

MacLean Electrical Group Ltd
Peterseat Park,
Peterseat Drive,
Altens,
Aberdeen,
AB12 3HT
Limitation of Scope - Assembly of Junction boxes
Protection Concepts - Ex 'e' 'tb'

Piemme Broker SRL
SP 181 Angolo SP 201 11
I-26833 Merlino (LO)
Limitation of Scope - Assembly of Junction boxes
Protection Concepts - Ex 'e' 'tb'

Power Wholesale Ltd
102 High Street West
Gateshead
Tyne & Wear
NE8 1NA
Limitation of Scope - Assembly of Junction boxes
Protection Concepts - Ex 'e' 'tb'

R&M Electrical Group Ltd
Baku White City Office Building
25E Nobel Avenue
Baku
AZ1025
Azerbaijan
Limitation of Scope - Assembly of Junction boxes
Protection Concepts - Ex 'e' 'tb'

R&M Electrical Group Ltd
Units 1&2, 362A Spring Road
Sholing
Southampton
SO19 2PB
Limitation of Scope - Assembly of Junction boxes
Protection Concepts - Ex 'e' 'tb'

Scattergood and Johnson Ltd
Lowfields Road
Leeds
LS12 6ET
Limitation of Scope - Assembly of Junction boxes
Protection Concepts - Ex 'e' 'tb'

Wellhead Electrical Supplies Limited
Unit 4d Dyce Industrial Park,
Wellheads Crescent,
Wellheads Industrial Estate,
Aberdeen,
AB21 7GA
Limitation of Scope - Assembly of Junction boxes
Protection Concepts - Ex 'e' 'tb'

AL Kiyumi Switchgear LLC
Plot No 125
Falaj Al-Ouhi
Sohar
PO Box 470, Postal Code 322
Falaj Al-Qabail
Sohar
Sultanate of Oman



IECEX Quality Assessment Report Summary

QAR Ref. No.:

GB/BAS/QAR06.0061/10

Page 5 of 5

Limitation of Scope - Assembly of Junction boxes
Protection Concepts - Ex 'e' 'tb'

Arabian Falcon Electrical Equipment LLC
PO Box 30569
Warehouse P26
M-44 Mussafah
Abu Dhabi
UAE

Limitation of Scope - Assembly of Junction boxes
Protection Concepts - Ex 'e' 'tb'

Killark
A Division of Hubbell Incorporated (Delaware)
2112 Fenton Logistics Park Blvd
Fenton, MO
63026
USA
Limitation of Scope - Assembly of Junction boxes
Protection Concepts - Ex 'e' 'tb'

Hawke Asia Pacific Pte Ltd- A Division of Hubble Ltd
130 Joo Seng Road #03-02
Singapore
368357
Singapore
Limitation of Scope - Assembly of Junction boxes
Protection Concepts - Ex 'e' 'tb'