

# BANDING AND BUCKLES

SECURE BRACKETS/EQUIPMENT TO POLES



## BANDING

- Supplied in 100' length, coiled in box
- 201 Stainless Steel
- Sizes: 1/2" x .03", 5/8" x .03", 3/4" x .03", 3/4" x .04", 1" x .04", 1 1/4" x .04"
- Skived edges to remove burrs



## INSTRUCTIONS



**Step 1:** Insert banding into buckle bend banding under buckle



**Step 2:** Wrap pole bringing banding through the buckle a second time



**Step 3:** Tighten banding with tool and cut excess banding



**Step 4:** Fold excess banding between ears and hammer ears securing excess banding

## BUCKLES

- 1/2", 5/8", and 3/4"
  - 201 Stainless Steel
  - 100/box
- 3/4" (Heavy), 1", and 1 1/4"
  - 304 Stainless Steel
  - 25/box

## BANDING

PART NUMBER	DESCRIPTION
C12201SSB100	Banding 1/2" x .03" x 100'
C58201SSB100	Banding 5/8" x .03" x 100'
C34201SSB100	Banding 3/4" x .03" x 100'
C34201SSB100G	Banding 3/4" x .04" x 100'
C100201SSB100	Banding 1" x .04" x 100'
C114201SSB100	Banding 1 1/4" x .04" x 100'

## BUCKLES

PART NUMBER	DESCRIPTION
PSC2080557	Buckle, 1/2"
PSC2080558	Buckle, 5/8"
PSC2080559	Buckle, 3/4"
PSC2080560	Buckle, 3/4" Heavy
PSC2080561	Buckle, 1"
PSC2080562	Buckle, 1 1/4"



hubbelpowersystems.com

For product inquiries, please contact your local sales representative or customer service representative.

©2018 Hubbell Incorporated. Because Hubbell has a policy of continuous product improvement, we reserve the right to change design and specifications without notice. Printed in the U.S.A. | SF\_06\_109E