

15<sup>th</sup> of March 2022

**PRODUCT ADVISORY**

**TROLEX TX6383 INCORRECT CERTIFICATE OF CONFORMITY NUMBER**

It has been found that a small number of TX6383 have been sent to customers with an incorrect certificate of conformity number on their label. The incorrect certificate of conformity number issued was ANZEx 11.3021X whereas the correct certificate of conformity number should be ANZEx 12.3021X.



**INCORRECT ANZEx LABEL**



**CORRECT ANZEx LABEL**

**Figure 1 TX6383 Marking Plate**

Austdac recommends that all TX6383 labels are checked to confirm that they have the correct ANZEx certificate of conformity number fitted (ANZEx 12.3021X). If the label has the incorrect certificate of conformity number please contact Austdac to arrange for a replacement label to be fitted.

For any further information please contact Austdac ( [austdac.nsw@austdac.com.au](mailto:austdac.nsw@austdac.com.au) ) or Peter Chan ( [plchan@austdac.com.au](mailto:plchan@austdac.com.au) ).

Regards



Peter Chan  
Engineering Manager  
[plchan@austdac.com.au](mailto:plchan@austdac.com.au)  
(02) 8851 5072