

No Burn Permit or Field Welding!

Irreversible, multi-functional ground rod connection

Product Introduction

The QuikTap™ connection features a wire exothermically welded to a ground rod coupling and ready for installation. The connection can be made by using a ground rod driver to compress the coupling onto the ground rod, providing a convenient and safe irreversible connection. This is a quick and easy way to install in the field without the need for a burn permit and also reduces concerns regarding hazardous materials and critical equipment.



Features & Benefits

- Irreversible connection no maintenance
- No need to weld in the field
- No burn permit needed
- Perfect for volatile or hazardous job sites
- Compatible with most ground rod types and configurations
- UL 467 for Grounding and Bonding; Rated for Direct Burial in Earth or concrete
- Easy to install Low Labor Cost

Customer Service 1-800-346-4175 | Tool Service Center 1-800-426-8720 | Technical Services 1-800-451-4956 | www.burndy.com



