



Hubbell Building Automation
Low Voltage Sensors (devices)
Requires 33mA each

NOTE:

1. DO NOT attempt to power more than 4 devices, be it sensors or slave packs, from a single power pack.

LOIRHB 1-circuit with 1 to 4 sensors

Hubbell Building Automation, Inc.