

INSTALLATION, OPERATION & MAINTENANCE DATA SHEET

SERIES SPARTAN POLE

Harsh & Hazardous



GENERAL GUIDELINES

- Please read the following instruction carefully and use the product accordingly.
- This summary may not include every detail of all variations and considered steps. Please contact us when further information and help are needed.

Suitable for use in Class I Div. 2 when installed in accordance to NEC 501. E27731 Type 3R Rated 250mph



TOOLS REQUIRED:





INSTALLATION, OPERATION & MAINTENANCE DATA SHEET

SERIES SPARTAN POLE



ATTACH THE RETROFITTER TO THE LIGHT POLE.

THE MIDDLE OF THE HINGE SHOULD BE APPROX 2" ABOVE THE HANDRAIL



LINE THE CUTTER UP WITH THE MIDDLE OF THE HINGE AND CUT THE POLE





LOOSEN THE LOCK BOLT AND OPERATE THE CAM MECHANISM





LOWER THE POLE 90 DEGREES UNTIL THE HINGE IS FULLY OPEN



UNDO THE WIRING AND REMOVE THE OLD FIXTURE

Vantage[°] Technology

P/N KIL00921301 FORM NO. K1301 04/21 ERO 8-018-21





Page 2 of 4

Harsh & Hazardous



INSTALLATION, OPERATION & MAINTENANCE DATA SHEET


SERIES SPARTAN POLE



REMOVE WIRING FROM POLE AND REMOVE POLE FROM CLAMP



REMOVE THE RETROFITTER FROM THE BOTTOM POLE



THREAD THE WIRE THROUGH THE HINGE



INSTALL THE HINGE ON THE BOTTOM POLE.

THERE IS NO NEED TO DEBUR THE HINGE INTERNAL POLE SOCKETS PROTECT THE CABLE

ATTACH AND WIRE

THE NEW FIXTURE

Vantage° Technology



THREAD THE CABLE UP THE TOP POLE AND INSERT THE POLE INTO THE HINGE

P/N KIL00921301 FORM NO. K1301 04/21 ERO 8-018-21



Page 3 of 4



Harsh & Hazardous



INSTALLATION, OPERATION & MAINTENANCE DATA SHEET

SERIES SPARTAN POLE



RAISE THE POLE



TIGHTEN THE HINGE TOP SET SCREWS. TIGHTEN THE LOCK BOLT

P/N KIL00921301 FORM NO. K1301 04/21 ERO 8-018-21

Page 4 of 4



Vantage[®] Technology

Harsh & Hazardous