


The INSTALLATION INSTRUCTIONS associated with this PDS drawing is an electronic file located on the Hubbell website at www.hubbellwiringsystems.com/instr

NOTES:

1. THIS DWG IS FOR HUBBELL/SAP REV. CONTROL AND RECORDING ONLY.
2. THE REV. (MONTH/YEAR) DATES ON THIS DWG & INSTALLATION INSTRUCTIONS SHALL COINCIDE WITH EACH OTHER.
3. THE ORIGINAL DOCUMENT AND PDF COPY ARE LOCATED IN SECURED FOLDERS G:\Released\INSTRUCT AND S:\INSTSHTS RESPECTIVELY FOR REFERENCE AND COPIES.

PDS NO.		
PDS-3056		
SIZE A	SHEET 1	OF 1
TITLE QR INSTALLATION INSTRUCTIONS		
 WIRING DEVICE-KELLEMS HUBBELL INCORPORATED SHELTON, CT		
TOLERANCES UNLESS OTHERWISE SPECIFIED .XX = ± .01 .XXX = ± .005 .XXXX = ± .0025 ANGLE TOL. ±1'	DR. BY AMS	SCALE
	CHK. BY DL	DATE 7/18/23
	PROJECT NO. NPD-3791	
SUB.	REVISIONS	
1	8/3/23 INITIAL RELEASE PER DCN 230802032315 AMS DL	