

HUBBELL FIRE-RATED ABANDONMENT PLATE

Cat. No. AP-42

This cover provides an approved method of abandoning Hubbell Poke-Through Catalog No. PT7XC with an above-floor service fitting and maintaining the fire rating of the installation.

NOTE: Abandoning an active Poke-Through must be done by a qualified electrician.

Instructions for Abandoning

1. Disconnect power to Poke-Through junction box below the floor and disconnect telephone/data service and above-floor fitting.
2. From floor below, disconnect wires inside Poke-Through junction box or EMT conduit. Also remove telephone/data wires.
3. Install Plate AP-42 using two (2) pan head screws removed in Step 1.

Hubbell Incorporated
Bridgeport, CT 06605
(203) 337-3100

PD1105 Printed in U.S.A. 4/81



Wiring Device Division