

OPGW DEAD-END

INSTALLATION INSTRUCTIONS



- 1) Remove bolts form one side of Dead-End.
- 2) Slip OPGW under keepers.



4) Be certain that the chamfered edge of the keeper is facing forward toward the span end of the Dead-End



- 3) Replace bolts that were removed.
- 5) WARNING. Tighten bolts evenly to prevent misaligned keepers.
- 6) Starting at the front of the dead end:
- -Tighten each bolt sequentially to approx. 5ft lbs.
- -Repeat this sequence and tighten each bolt to approx. **25 ft. lbs**.
- -Finally tighten each bolt sequentially until the shear head breaks off. (approx. 350" lbs.)
- 6) See photos below that illustrate results from proper bolt tightening vs. improper tightening.



PROPER BOLT TIGHTENING RESULTS



IMPROPER BOLT TIGHTENING RESULTS