



SP2 1.4.0

Bug Fixes:

- None

Added Features/Enhancements:

- **Added ability to communicate with GUDA**
SP2 stations will now have limited programming capability via GAI-Tronics' GUDA configuration tool.
- **Added TONEON and TONEOFF commands**
The new TONEON and TONEOFF commands can be used in the command line interface mode to simulate amplifier failure for troubleshooting purposes.